



Simply Connected

Tech Note: Upgrading the Firmware of your Luxul Xen™ XAP Wireless Access Point

Version 1.0

SCOPE/PURPOSE

Instructions on upgrading the Firmware of your Luxul XAP Wireless Access Point.

FIRMWARE UPGRADE

The screenshot shows the Luxul XenSmart web interface. At the top left is the Luxul logo with the tagline "Simply Connected". At the top right is the "XenSmart™" logo. On the left is a navigation menu with the following items:

- Quick Setup
- ▼ Wireless
 - Settings
 - ▼ Profiles
 - SSID 1
 - SSID 2
 - SSID 3
 - SSID 4
 - SSID 5
 - SSID 6
 - SSID 7
 - SSID 8
- ▼ Maintenance
 - Upgrade
 - Factory Defaults
 - Backup/Restore
 - ▶ Status

The main content area is titled "Firmware Upgrade" and contains a form with the following elements:

- "Select a file" label with a question mark icon.
- A text input field.
- A "Browse..." button.
- An "Upgrade" button.

On the right side of the main content area, there is a text box with the following text:

Firmware Upgrade
Allows for the upgrade of the Firmware on the Luxul Xen™ Access Point. To check for new firmware updates, visit www.luxul.com/support

Firmware Upgrade: This page allows for the upgrade of the firmware on the XAP-1010. To check for firmware updates, visit www.luxul.com/support.

1. Go to the Luxul website and download the new version of firmware, <http://thebestsignal.com/downloads>
2. Click *Browse* to locate the firmware file on your computer
3. Click *Upgrade* to perform the update



WARNING! Do not power off the access point or computer being used during the upgrade or the access point may be damaged.

Troubleshooting and Support

After completing the above steps, your Luxul Xen Access Points should be operating in Bridge Mode. If you experience any difficulty after completing this setup, please contact Luxul Support with any issues or questions.

Phone Support: 801-822-5450

Email: support@luxul.com

Information on this document supersedes all previous versions. Products and documents subject to change without notice. Products may be discontinued without notice.